


**SEWING MACHINE TABLE**  
**COMFORT 7 ( C 7+ )**  
**СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ**



# ***SYMBOLS***



***ATTENTION***

***ВНИМАНИЕ***




***ASSEMBLY & ADJUSTMENT***

***СБОРКА РЕГУЛИРОВКА***




***OPERATION***

***ЭКСПЛУАТАЦИЯ***



***INDICATING MARK***






***ОБОЗНАЧЕНИЕ***



***EVEN SURFACE***

***РОВНАЯ ПОВЕРХНОСТЬ***

010001	1x	010002	1x	010003	1x	010004	1x
010006	1x	010007	1x	010008	1x	010010	1x
010011	1x	010012	1x	010013	1x	010015	1x
010023	1x	010024	1x	010025	1x	010026	1x
010027	1x	010028	1x	010030	1x	010031	1x
010032	1x						







 <b>020001</b> <b>4x</b>	 <b>020002</b> <b>4x</b>	 <b>020003</b> <b>2x</b>	 <b>020004</b> <b>2x</b>	 <b>020005</b> <b>2x</b>
--	--	---	---	---

 <b>020006</b> <b>2x</b>	 <b>020008</b> <b>2x</b>	 <b>020010</b> <b>L 660</b> <b>2x</b>	 <b>020011</b> <b>1x</b>	 <b>020012</b> <b>1x</b>
---	---	---	---	---





<b>3x</b> <b>020013 CR</b> 	<b>3x</b> <b>020013 CL</b> 
---	---






<b>3x</b> <b>020015 DR</b> 	<b>3x</b> <b>020015 DL</b> 
---	---

<b>2x</b> <b>020016</b> 
---

<b>030001</b>  <b>3 * 16</b> <b>58x</b>	<b>030002</b>  <b>3,5 * 16</b> <b>40x</b>	<b>030003</b>  <b>6,2 * 50</b> <b>18x</b>	<b>030004</b>  <b>φ5 * 30</b> <b>8x</b>	<b>030005</b>  <b>4,2 * 16</b> <b>10x</b>	<b>030006</b>  <b>2,9 * 13</b> <b>6x</b>
---	---	---	--	---	--

<b>030008</b>  <b>φ4</b> <b>4x</b>	<b>030009</b>  <b>M4 * 20</b> <b>4x</b>	<b>030011</b>  <b>φ15</b> <b>18x</b>	<b>030012</b>  <b>φ18</b> <b>12x</b>	<b>030013</b>  <b>L = 35</b> <b>12x</b>	<b>030014</b>  <b>φ15 h12</b> <b>13x</b>
--	---	--	--	---	--

<b>030015</b>  <b>φ8 * 30</b> <b>14x</b>	<b>030016</b>  <b>φ8 * 30</b> <b>2x</b>	<b>030017</b>  <b>φ15 h12</b> <b>2x</b>	<b>030018</b>  <b>φ8 * 15</b> <b>1x</b>
--	---	---	--




<p><b>1 x</b>                      <b>050001</b></p> 	<p><b>1 x</b>                      <b>050002</b></p> 
<p><b>1 x</b>                      <b>050004</b></p> 	<p><b>1 x</b>                      <b>050003</b></p>  <p><b>2 x</b>                      <b>050005</b></p> 


<p><b>1 x</b>  <b>S4</b></p>
---















**COMFORT 7+**



<p><b>010018</b>    <b>1x</b></p> <p><b>010019</b>    <b>1x</b></p>	<p><b>020001</b></p> <p><b>1x</b></p> 	<p><b>5x</b>    <b>020019</b></p> 	<p><b>030004</b></p>  <p><math>\phi 5 * 30</math></p> <p><b>1x</b></p>	<p><b>030005</b></p>  <p><b>4,2 * 16</b></p> <p><b>20x</b></p>
---	--	---	---	---













S 4







**A****32 A****1 x 050003****1 x 050002****2 x**   
**030005****B****32 B****1 x 050003****1 x 050002****2 x**   
**030005****33 A****2 x**   
**030005****1 x 050001****33 B****2 x**   
**030005****1 x 050001**



# COMFORT 7 +


**36** 12 x  030005




**3 x** 020019


**35** 8 x  030005


**2 x** 020019





**34** 020001

**1x** 



**1x**  030004



4



5A



5B

